

CERTIFICATE

No. Z2 17 03 53696 01940

Holder of Certificate:

KOMPAN A/S

C.F. Tietgens Boulevard 32C

5220 Odense SØ

DENMARK



Certification Mark:



Product:

Seesaw

Rocking equipment

The product was tested on a voluntary basis and complies with the essential requirements. The certification mark shown above can be affixed on the product. It is not permitted to alter the certification mark in any way. In addition the certification holder must not transfer the certificate to third parties. See also notes overleaf.

Test report no.:

713099767-13

Valid until:

2022-03-27

2017-03-29 Date,

(Tobias Hofmann)

Page 1 of 2





CERTIFICATE No. Z2 17 03 53696 01940

Model(s):

GXY935000, GXY934000, M194,

M188, M189, M190, M195

Parameters:

GXY934000:

Oscillating seesaws with cardan joint and rubber dampers,

base with middle pole, handles Ø 38mm.

GXY935000:

The balance equipment is movable supported with rubber dampers. The balance board is plastic coated.

Length: 1740mm Height: 558mm Width: 919mm

M194:

Type 3A seesaw, standing seesaw with two user positions.

Frame of Ø33,7x2,25 tube and 6mm steel plate.

Pole of 88,6x3,2mm steel tube

M188, M189:

Springrider with a rubber damping beneath the seat.

Body made of 19mm HDPE plates.

M190, M195:

18mm steel spring. Body made of 19mm HDPE plates or PE Rotary molded body, 19mm PP plates with foamed core or

rotary molded HDPE body.

Tested

according to:

DIN EN 1176-1:2008

EN 1176-1:2008 DIN EN 1176-6:2008 EN 1176-6:2008

Production Facility(ies):

63062

Page 2 of 2